

*Get that old feeling of a new machine -  
- Again . . .*

---

---



**Airco burning machine with  
a Burny 5, HT2000 Plasma  
punch marker and 4 oxy/fuel torches  
10 ft. wide, 65 ft. long**



**Burdox burning machine with  
a Burny 5, HT2000 Plasma  
punch marker and 4 oxy/fuel torches  
10 ft. wide, 65 ft. long**



**Airco burning machine with  
a Burny 5, Merlin 6000 Plasma,  
punch marker and 2 oxy/fuel torches  
10 ft. wide, 40 ft. long**



**Burdox burning machine with  
a CMC Burny 3 controller  
2 Hypertherm HT2000 Plasmas  
10 ft. wide, 100 ft. long**



**Heath burning machine with  
a Burny 10, punch marker,  
and HD3070 HyDef Plasma  
6 ft. wide, 12 ft. long**



**Linde CM-100 burning machine  
with a Burny 10, Max 200 Plasma  
Arc Writer and 2 oxy/fuel torches  
23 ft. wide, 20 ft. long**